

SERVICE PARTS LIST

BULLETIN NO. 54-05-5315

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS REVISED BULLETIN DATE July 2017 SDS MAX DUST EXTRACTION ATTACHMENT WIRING INSTRUCTION STARTING SERIAL NO CATALOG NO. 5317-DE

EXAMPLE:

 $00 \frac{1}{0}$ Component Parts (Small #) Are Included When Ordering The Assembly (Large #).




FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
1	43-31-0015	Brush Ring	(1)
2	10-20-0139	Nameplate	(1)
3	49-90-1959	Hose Clip Adaptor	(1)

FIG. NOTES

A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.